

241

Repair Management
BY NAVISTAR

STADIUM INTL S & S, LLC

105 7TH NORTH STREET - LIVERPOOL, NY 13088

Phone: (1) 315-4758471 - Fax: (1) 315-4754150

Estimate Number: 2683002 - RO Number: 6035557

Service Writer: Christopher Joynt - Date: 10/9/2019 10:47 AM (C)



Currency: USD

Unit No: 241

VIN: 1HTWAAAR26J238920
Model: 7300 SFA 4X2
Engine: INTL DT466 245HP/2600 GOV
Make: International
Delivered: 7/26/2005
In Service: 14 Years 2 Months
Mileage: 96398 Eng Hrs: 0

Recall/AFC: No

Contact Name:
Position:
Phone:
E-Mail:
PO Number:

Operation Section A	Labor Cost	Parts Cost	Core Charge	Total Cost
Computer Hook Up - Fixed Cost	\$0.00	\$0.00	\$0.00	\$50.00
Fuel Injector(S) (ELECTRONIC ENGINES), Replace (6) INJECTOR ASSEMBLY, REMANUFACTURED 466 HIGH HP (1) GASKET ASSEMBLY VALVE COVER COVER /UVC HARNESS	\$331.25	\$2,812.74	\$0.00	\$3,143.99
Road Test / Test Drive - ROAD TEST AND RECHECK AFTER REPAIRS ARE MADE	\$0.00	\$0.00	\$0.00	\$132.50
DIAGNOSE ENGINE PROBLEM	\$278.25	\$0.00	\$0.00	\$278.25

Complaint:	Not Available
Cause:	Not Available
Correction:	Not Available

Operation Section B	Labor Cost	Parts Cost	Core Charge	Total Cost
Injector Oil Inlet Adaptor (PUCK), Replace (6) ADAPTER ASSEMBLY, INJECTION OIL INLET	\$132.50	\$238.20	\$0.00	\$370.70

Complaint:	Not Available
Cause:	Not Available
Correction:	Not Available

Operation Section C	Labor Cost	Parts Cost	Core Charge	Total Cost
Engine Oil Pump, Replace (1) KIT, REMANUFACTURED HIGH PRESSURE PUMP 12CC (1) FILTER,KIT FUEL FILTER ELEMENT	\$530.00	\$1,435.81	\$0.00	\$1,965.81

Complaint:	Not Available
Cause:	Not Available
Correction:	Not Available

Notes: [10/9/2019 10:47 AM] - Dealer: ENGINE SMOKES WHEN FIRST STARTS THEN SKIPS

Summary	
Parts:	\$4,486.75
Core:	\$0.00
Labor:	\$1,272.00
Other Items:	\$182.50
Shop:	\$179.47
Tax:	\$0.00
TOTAL:	\$6,120.72

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish