

Keep this document to show to the police and courts.

MV-639TR (10/15) NEW YORK STATE REGISTRATION DOCUMENT



G PSD
AY8493 **PERM**
2017 CHEVR NONTRANSFERABLE
SUBN GY 2GNFLEEK6H6279229
003867 G 4 GV116375 JAN 30 2017
Wt/Seats Fuel/Cyl CAJ MLN359

Expires PERM

FRANKLIN CTY SWCD
151 FINNEY BLVD EXEMPT
MALONE NY 12953

ANNUAL CHG
AMT PAID (ENCL ADD CHG)

GV116375 VOID IF ALTERED EXCEPT FOR ADDRESS

0.00



Invoice #

Medione, Mr 12953

Office (518) 483-1140

Case: 15181-283-2950

Fax: (518) 483-6645

Date of Order:	8-29-22
Year, Make, Model:	17' Chevy Equinox
Miles/gal./Hours:	48823
Plate No.:	AY8493

To: Franklin County Soil & Water Conservation District

251 Finney Boulevard

Malone, NY 12953

[illegible]

Labor	Hours	Rate	Amount
<i>Séan</i>			

Total Other \$

Job Total \$

Description of Work

Service 225 65R17

R+R all paid + noting. R+R park broke
shoes + hardware.

Sean

[illegible]

Franklin County Highway Dept.

14981 State Route 30

Office (518) 483-1140

Grade: (518) 483-4950

Fax: (516) 483-6645

Date of Order:	1-29-22
Year, Make, Model:	17 Chevy Equinox
Mileage/Hours:	44438
Plate No.:	71Y8Y93
Vehicle No.	

To: Franklin County Soil & Water Conservation District

151 Finne; Boulevard

Miaione, NY 12953

26N1EEK6H6279229

Terms

Description of Work

NYSL Service

Labor	Hours	Rate	Amount
Jean			

Total Labor \$

Total Other \$

Total Materials

Job Total \$



STATE OF NEW YORK



VEHICLE INSPECTION REPORT

Print Date: 1/20/2021 2:38:50 PM Inspection Date: 1/20/2021 2:24:38 PM Expiration Date: 01/31/2022 Inspection Type: Initial Inspection Version: 19.11.05

VEHICLE DETAILS	VIN	2GNFLEEK6H6279229	MODEL	Equinox	FUEL	G	
	YEAR	2017	PLATE	AY8493	WEIGHT	0 - 8500 lbs	
	MAKE	Chevrolet	MILEAGE	39,748	EIR #	411788	
INSPECTION SUMMARY	Inspection Result		Safety	Emission	Sticker Number		Fee
	PASS		PASS	PASS	LE: 1363562		\$21.00

Congratulations, your vehicle has passed its annual New York State inspection. Please retain this receipt for your records. You may be required to present this receipt in order to renew your vehicle registration.

Wheel Removed
1: L/F

INFO

** The Result Of the inspection will be transmitted electronically To DMV, usually within 24 hours.

Recall Advisory Notice Any recall information included in this report is based on information supplied to the New York Vehicle Inspection Program at the time of inspection. The program depends on its sources for the accuracy and reliability of its information. Therefore, no responsibility is assumed by NY DMV or its agents for errors or omissions in this report. To check for vehicle recalls, go to NHTSA.gov/recalls and enter your vehicle's VIN (vehicle identification number). NHTSA.gov/recalls will quickly tell you if your vehicle has not been repaired as part of a safety recall in the last 15 years. In case of an open recall, you may visit a local new car dealer who sells and repairs your brand of vehicle to have it repaired at no expense.

VEHICLE INSPECTION QUESTIONS:

For additional information please contact the Department of Motor Vehicles at website address: <http://www.dmv.ny.gov>.
Or by telephone number: 518-486-9786.



FACILITY INFO	Inspector Number	NYVIP2 Record Number	Online/Offline	DMV Record Match
	7RY6	585	Online	V
	Facility Number	Facility Name	Facility Phone Number	Analyzer Number
	7010603	FRANKLIN COUNTY OF	5184834950	NY00005860
	Address	14981 STATE ROUTE 30, MALONE		Name/RO#:

Invoice #

Palatone, NY 12953

Palatone, NY 12953

Office: (515) 483-1140

For more: (518) 483-4350

Fax: 518-493-6645

To: Franklin County Soil & Water Conservation District

Milone, NY 12953

Description of Work

1451

Job Total \$

Invoice #

Maione. NY 12955

Gerçek: (518) 483-4950

Fax: (518) 483-5545

Date of Order:	1/27/96
Year, Make, Model:	1987 Ford Bronco
Mileage/Hours:	37044
Plate No.:	A8493

Ta Franklin County Soil & Water Conservation District

151 Finney Boulevard

Malone, NY 12953

Terms

Description of Work

Securite chat cells and AHS installation

[illegible]

Labor	Hours	Rate	Amount
<i>Old</i>			

Total Labor \$

Total Other \$

Total Material \$

Job Total \$



STATE OF NEW YORK



VEHICLE INSPECTION REPORT

Print Date: 1/27/2020 10:15:20 AM Inspection Date: 1/27/2020 9:51:22 AM Expiration Date: 01/31/2021 Inspection Type: Initial Inspection Version: 19.05.02

VEHICLE DETAILS	VIN	2GNFLEEK6H6279229	MODEL	Equinox	FUEL	G	
	YEAR	2017	PLATE	AY8492	WEIGHT	0 - 8500 lbs	
	MAKE	Chevrolet	MILEAGE	37,044	EIR #	410988	
INSPECTION SUMMARY	Inspection Result		Safety	Emission	Sticker Number		Fee
	PASS		PASS	PASS	LE: 1085344		\$21.00

Congratulations, your vehicle has passed its annual New York State inspection. Please retain this receipt for your records. You may be required to present this receipt in order to renew your vehicle registration.

Wheel Removed

1: L/F

INFO

** The Result Of the inspection will be transmitted electronically To DMV, usually within 24 hours.

Recall Advisory Notice Any recall information included in this report is based on information supplied to the New York Vehicle Inspection Program at the time of inspection. The program depends on its sources for the accuracy and reliability of its information. Therefore, no responsibility is assumed by NY DMV or its agents for errors or omissions in this report. To check for vehicle recalls, go to NHTSA.gov/recalls and enter your vehicle's VIN (vehicle identification number). NHTSA.gov/recalls will quickly tell you if your vehicle has not been repaired as part of a safety recall in the last 15 years. In case of an open recall, you may visit a local new car dealer who sells and repairs your brand of vehicle to have it repaired at no expense.

VEHICLE INSPECTION QUESTIONS:

For additional information please contact the Department of Motor Vehicles at website address: <http://www.dmv.ny.gov>.
Or by telephone number: 518-486-9786.



FACILITY INFO	Inspector Number	NYVIP2 Record Number	Online/Offline	DMV Record Match
	46PB	518	Online	V
	Facility Number	Facility Name	Facility Phone Number	Analyzer Number
	7010603	FRANKLIN COUNTY OF	5184834950	NY00005860
	Address	14981 STATE ROUTE 30, MALONE		Name/RO#:

Invoice #

Melrose, NY 12553

Office: (518) 483-1110

Garage: (518) 483-2550

Fax: (515) 483-6645

Date of Order:	8-13-19
Year, Make, Model:	2017 Chevy Equinox
Mileage/Hours:	31106
Plate No.:	8-13-19 A Y8493

To: Franklin County Soil & Water Conservation District

151 Finney Boulevard

Malone, NY 12953

Terms

Description of Work

Service TR MP1
Expenses paid + non paid + notations

Labor	Hours	Rate	Amount
SSA			

Total Labor \$

Total Other \$

Total Material \$

Job Total \$

Invoice #

Maddone, R.J. 1953

Date of Order:	May 9, 2019
Year, Make, Model:	2019 Chevy Equinox

Year, Make, Model:	2014 Chevy Equinox
Mileage/Hours:	22,212

Year, Make, Model:	2014 Chevy Equinox
Mileage/Hours:	22,212
Plate No.:	AC 8493

150 Finney Boulevard

Terms

Description of Work

[illegible]

Labor	Hours	Rate	Amount
Total Labor \$		Total Other \$	
Total Material \$		Job Total \$	

[illegible]

Franklin County Highway Dept.

14951 State Route 30

Malone, NY 12952

Office (515) 455-1120

சோதனை : 15161-283-2-250

Fax: (516) 483-5645

Date of Order:	June 19, 2018
Year, Make, Model	2017 Chevy Equinox
Mileage/Hours:	14,878
Plate No.:	AY 4983

To: Franklin County Soil & Water Conservation District

151 FIFTH ST. SEWARD

Malone, NY 12953

Terms			
Description of Work			
Total Labor \$		Total Other \$	
Total Material \$		Job Total \$	

[illegible]

Franklin County Highway Dept.

Invoice #

15951 Route 30

Macrone, P.V. 2253

Office 1516; 466-1146

Geocode: (516) 333-9560

Fax: (518) 483-6645

Date of Order:	2/21/18
Year, Make, Model	17 Chevy Cobalt
Mileage/Hours	9936
Plate No.	A 8493

TO: Franklin County Soil & Water Conservation District

551 Finley Boulevard

Malone, NY 12953

Terms

Description of Work

Service, US insertion and PM staff


Labor	Hours	Rate	Amount
<i>9/1/02</i>			

Total Labor \$

Total Other \$

Total Materials

Job Totals



STATE OF NEW YORK



VEHICLE INSPECTION REPORT

Print Date: 2/22/2018 8:44:06 AM Inspection Date: 2/22/2018 8:28:02 AM Expiration Date: 02/28/2019 Inspection Type: Initial Inspection Version: 17.12.02

VEHICLE DETAILS	VIN	2GNFLEEK6H6279229	MODEL	Equinox	FUEL	G
	YEAR	2017	PLATE	AY8493	WEIGHT	0 - 8500 lbs
	MAKE	Chevrolet	MILEAGE	9,934	EIR #	N/A

INSPECTION SUMMARY	Inspection Result	Safety	Emission	Sticker Number	Fee
	PASS	PASS	N/A	SI: 10242922	\$10.00

INFO

Congratulations, your vehicle has passed its annual New York State inspection. Please retain this receipt for your records. You may be required to present this receipt in order to renew your vehicle registration.

Wheel Removed

- 1: L/F
- 2: R/F
- 3: L/R
- 4: R/R

The Result of the inspection will be transmitted electronically to DMV, usually within 24 hours.

Recall Advisory - Your vehicle may be subject to a manufacturer's safety recall. To check, go to safercar.gov and enter your vehicle's VIN (Vehicle Identification Number). Safercar.gov will quickly tell you if your vehicle has not been repaired as part of a safety recall in the last 15 years. In case of an open recall on your vehicle, you may visit a local new car dealer who sells and repairs your brand of vehicle to have it repaired at no expense.

VEHICLE INSPECTION QUESTIONS:

For additional information please contact the Department of Motor Vehicles at website address: <http://www.dmv.ny.gov>.
Or by telephone number: 518-486-9786.



FACILITY INFO	Inspector Number	NYVIP2 Record Number	Online/Offline	DMV Record Match
	3YT2	388	Online	V
	Facility Number	Facility Name	Facility Phone Number	Analyzer Number
	7010603	FRANKLIN COUNTY OF	5184834950	NY00005860
	Address	14981 STATE ROUTE 30, MALONE		Name/RO#:

FRANKLIN COUNTY HIGHWAY DEPARTMENT MULTI-POINT INSPECTION

Department: Soil & Water Vehicle Year/Model/ID No.: 2017 Equinox
 Vehicle VIN No.: 2GNFLEEK16H6279229 Mileage: 4852 Date: July 31, 2017

Checked and OK at this time

May Require Future Attention

Requires Immediate Attention

Maintenance Services Performed	
<input type="checkbox"/> Accessory Drive Belt(s)	<input checked="" type="checkbox"/> Change Oil Filter
<input type="checkbox"/> Replace Cabin Air Filter	<input type="checkbox"/> Replace Spark Plugs
<input type="checkbox"/> Replace Engine Air Filter	<input checked="" type="checkbox"/> Tire Rotation
<input type="checkbox"/> Change Engine Coolant	<input type="checkbox"/> Transmission Filter (change)
<input type="checkbox"/> Change Fuel Filter	<input type="checkbox"/> Transmission Fluid (change)
<input checked="" type="checkbox"/> Oil Change	<input type="checkbox"/> Other

Comments: _____

Recommended Scheduled Maintenance Services					
OK Fill	OK Fill	OK Fill	OK Fill	OK Fill	OK Fill
<input type="checkbox"/> Engine Oil	<input checked="" type="checkbox"/> Power Steering	<input checked="" type="checkbox"/> Transmission	<input type="checkbox"/> Brake Reservoir	<input checked="" type="checkbox"/> Window Washer	<input type="checkbox"/> Coolant

Safety & Component Checks	
<input checked="" type="checkbox"/>	Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
<input checked="" type="checkbox"/>	Radiator, heater and air conditioning hoses for leaks and damages
<input checked="" type="checkbox"/>	Windshield for cracks, chips and pitting
<input checked="" type="checkbox"/>	Accessory drive belt(s)
<input checked="" type="checkbox"/>	Brake system (including lines, hoses and parking brake) and wheel end for end-play and bearing noise
<input type="checkbox"/>	Clutch operation (if equipped)
<input checked="" type="checkbox"/>	Constant velocity (CV) drive axle boots (if equipped)
<input checked="" type="checkbox"/>	Drive shaft, transmission, u-joint(s) and shaft linkage (if equipped) and lubricate (as needed)
<input checked="" type="checkbox"/>	Engine cooling system, hoses and clamps
<input checked="" type="checkbox"/>	Exhaust system (leaks, damage and/or loose parts)
<input type="checkbox"/>	Oil and/or fluid leaks
<input type="checkbox"/>	Shocks/struts and other suspension components for leaks and/or damage
<input type="checkbox"/>	Steering and/or steering linkage

State Inspection Due 11/31/2018

Comments: _____

Technician: DAE

State of Health		Condition of Terminals	
0%	100%	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Bad
530		(Clean if Necessary)	
550 CCA		Declined Battery <input type="checkbox"/>	

Chassis Brakes - Measurement Front/Rear Brake Linings			
LF	10mm	RF	10mm
LR	8mm	RR	8mm

Over 5mm or 7/32" (Disc)	Over 2mm or 3/32" (Drum)
3 to 5mm or 4/32" to 7/32" (Disc)	1.01 to 2mm or 2/32" to 3/32" (Drum)
Less than 3mm or 4/32" (Disc)	Less than 1mm or 2/32" (Drum)

☐ Brake Measurement not taken this service visit

Comments: _____

Tread Depth			
LF	<input checked="" type="checkbox"/> 7/32" or Greater	RF	<input checked="" type="checkbox"/> 7/32" or Greater
	<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
	<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
LR	<input checked="" type="checkbox"/> 7/32" or Greater	RR	<input checked="" type="checkbox"/> 7/32" or Greater
	<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
	<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less

Wear Pattern/Damage	
<input checked="" type="checkbox"/> LF	<input checked="" type="checkbox"/> RF
<input checked="" type="checkbox"/> LR	<input checked="" type="checkbox"/> RR

Tire Wear Indicators:

☐ Alignment Check Required ☐ Wheel Balance Required

Comments: _____

Tire Pressure Set to Factory Recommended PSI

35 ☐ Front ☐ Rear 35