

SCARBOROUGH SERVICE CENTER 1 GLASGOW ROAD SCARBOROUGH, ME 04074 PH: 207-883-9910

** Reprint **

Invoice: SCA013640.02

Date / Hour: 2/24/2023 3:47:16PM

Repair Order: 3640

Customer: 0603438000

Branch: SCA

Total Invoice: \$ 587.25

Charge Page 1 of 2

Bill To:

ECO MAINE

64 BLUEBERRY RD

PORTLAND, ME 04102-1924

P To: ECO MAINE

64 BLUEBERRY ROAD

PORTLAND, 1020-000d

Work. 2077731738

Shop: 0

Fax: 2077738296

Customer P/O:

Task:

ploof

Orig R/O; 0

Completion Date:

Unit Number: 36

Model Year: 2006

Make/Model: VOLVO Meter: '0 Miles 4

Type: TRACTOR

VIN. 4V5K99GH56N413820

001-01 INSPECTION AND ESTIMATE Complaint: look unit of for repair Items and Cyclinder leak

Department: SERVICECTR

Correction: LOOKED OVER UNIT FOUND, MULTIPLE ISSUES ADVISED CUSTOMER THAT UNIT HAD MULTIPLE ISSUE, MAINELY NEEDING A NEW DUMP BODY AND HYDROLIC SYSTEM, -1170

DEFECTS FOUND: Unit needs the following: Both rear wish bone torque rods Front brakes d plate support bracket. Power pump and pressure lines Front main seal is leaking Injector harness pass through is leaking Dump pump and valve are leaking Headboard and cab cover on body is rotted Tailgate lock plate is torn from body

Tailgate Right sight latch is broken

Supp. Part

Quantity

Total Parts:

Prid

Customer Tax 10: Detail Tax Info:

205003826

Total Labor:

.00 \$506.25

Total Shop Supplies:

\$81.00

Invoice Subtotal:

\$587.25

Total Tax: Tota voice:

\$0.00 \$587.25

Payment Method

Charge

Terms NET 30

Due Date:

Description / Ref Number

3/26/2023

Remit To:

SCARBOROUGH SERVICE CENTER

FLEETPRIDE

P.O. BOX 281811

ATLANTA, GA 30384-1811